


SmartGraph2 Professional

Automatic printing of various measuring points and transfer of data to proprietary computer program

Data export

Measuring data from the internal SmartGraph data format can be used for calculations. For this purposes there is a powerful export function for the selection of various data formats with different separators and arbitrary intervals.



Automatic print-out

Important and useful in case of many dataloggers. Herewith, any time interval for all dataloggers can be printed, different print-out options.



Modification of data indication

When the dew point is to be indicated on the OPUS display instead of the relative humidity, the conversion of the display is configured for this purpose.



Example

For the results of an export function (Excel table)

The screenshot shows the "ExportList - Editor" window. It contains a table with the following columns: "Date", "Start/End", and "Format". The data is as follows:

Date	Start/End	Format
01/01/2007	00:00:00	
01/01/2007	00:00:00	16.7
01/01/2007	00:10:00	
01/01/2007	00:10:00	16.6
01/01/2007	00:20:00	16.6
01/01/2007	00:30:00	
01/01/2007	00:30:00	16.6
01/01/2007	00:40:00	
01/01/2007	00:40:00	16.6
01/01/2007	00:50:00	16.6
01/01/2007	01:00:00	
01/01/2007	01:00:00	16.6
01/01/2007	01:10:00	
01/01/2007	01:10:00	16.6
01/01/2007	01:20:00	16.6
01/01/2007	01:30:00	
01/01/2007	01:30:00	16.6
01/01/2007	01:40:00	
01/01/2007	01:40:00	16.6
01/01/2007	01:50:00	16.6
01/01/2007	02:00:00	
01/01/2007	02:00:00	16.6
01/01/2007	02:10:00	
01/01/2007	02:10:00	16.6